In the following guide you will learn how to connect and begin using the BxCamera to provide gross images and measurements.

Step 1: Connect your camera

While no internet access is needed to use the camera, we do recommend connecting the camera to a computer with internet access in order to receive future updates.



Package Contents

1. BxCamera
2. USB-C power brick
3. USB-C power cable
4. Ethernet cable
5. USB-A to Ethernet Adapter
6. Cassette Adapter
7. Calibration Target
8. Focus Tool

Connecting the BxCamera

1. Connect to power then wait for lights to change from single light rotating, to edges lighting up in succession. (about 1 minute)
2. Connect the ethernet cable to the BxCamera and then into the USB-A dongle.
3. Connect USB-A dongle to computer (if your computer does not have USB-A, another adapter may be needed but is not provided).
4. Set up complete.

Step 2: Capture your first image

1. Ensure the BxCamera is properly connected to your computer (see step 1).
2. Open up a web browser on your computer (chrome recommended).
3. Navigate to camera.lumeadigital.com (https://camera.lumeadigital.com).
4. Place your specimen container in the center of the camera.
5. Select which device type you are imaging.
6. The BxCamera will capture and display the image and measurements in the default grossing template.
7. Export resulting measurement data and/or image (copy, download, print).
8. That's it! Click *Capture Next Specimen* button to do it again.

See the full manual → (https://resources.lumeadigital.com/manuals/bxcamera-stand-alone-manual/)